

78th Street Heritage Farm Preservation & Maintenance Plan

County Council Work Session, Aug. 8, 2018, 6th Floor Training Room

Public Service Center, 1300 Franklin St., Vancouver, WA





Clark County Community Planners

Jacqui Kamp Sharon Lumbantobing

AECOM (Consultant) Architectural Historians Patience Stuart



History of the property

Pioneer Farm – Anderson Donation Land Claim (1865-1871)



Pioneer Farm – Anderson Donation Land Claim (1865-1871)







Photo credits: Olive McCafferty Harris



1944




Present





These Two Men, having all their belongings in the trunk, boxes and flour sacks, are ready to leave the farm. Perhaps they have been given a job or have been sent travel money from a relative. Part of the job of the Harrises was to try to make contact with relatives and inform them of the plight of these unfortunates.

McCafferty Harris




All Ages Were Admitted to the farm from orphan children to old folks no longer able to work. This elderly man is smashing clods with the added weight of a little orphan passenger. The farm was productive, each resident contributing according to his ability. Young and old worked side by side.



Olive McCafferty Harris

Olive McCafferty Harris

Experimental Farm (1944-present)



78th Street Heritage Farm (2008-present)





ADMIN BUILDING

Washington State University Extension programs, staff and plant clinics are housed here.

2 GREENHOUSES

Master Gardener Foundation leases the greenhouse area and holds plant sales every May and September.

3 CERTIFIED **ORGANIC GARDEN**

WSU Master Gardeners maintains this site. Produce goes to local food banks and pantries.

PARTNERS IN CAREERS (PIC)

Roots to Road is a PIC program focusing on training, education and employment for veterans interested in small scale farming and business development.

SU EXTENSION **4-H RESTORATIVE COMMUNITY** SERVICE GARDEN

Approximately 25 plots are gardened by juveniles working off their community service requirements.

6 COMMUNITY GARDENS

84 plots of 20-foot by 20-foot. Annual rent is \$60 per plot. Rent includes water and parking. Local residents garden or farm the plots using pesticide-free methods.

CLARK COUNTY FOOD BANK

Volunteers plant, weed and harvest 10 acres of food crops. Approximately 33,000 people receive the produce in emergency food boxes; about 40% are children.

13 TERRACE DEMONSTRATION

This shows how to farm or garden on a slope using permaculture theories.

9 VIEW POINT

At the top of the hill on a clear day, vou can see three or four volcanic mountains.



INTERPRETIVE TRAIL PLAN

The county is designing interpretive exhibits and signs for a trail system that will wind through the 79-acre site. Visitors will be able to learn about the experiences of local pioneer settlers and poor farm residents, and how their lives led to the success of a local agricultural industry. Planning for the trail signs was paid for by a grant.



The cemetery contains the remains of 312

men, women and children buried between

1913 and 1937. Not all were residents of the

poor farm. Clark County provided funeral

family or whose relatives could not afford


and burial here for anyone who had no

the services.

Preservation Initiatives

Cemetery Remote Sensing project

- Determining correct cemetery boundaries
- Internments conform to plat diagram
- Plat generally represents an accurate view of burial locations
- Recommendation to move fence



Master Planning Efforts

78th Street Heritage Farm Master Plan

2010

Agriculture

Historic Preservation


Community Access

Sustainable Design

Education & Research




Interpretive Trail Planning




78TH STREET HERITAGE FARM interpretive trail plan

AUGUST 2011



Historic District

- National Register of Historic Places
- Washington Heritage
 Register
- Clark County Heritage
 Register



Preservation and Maintenance Plan

What is a Preservation & Maintenance Plan?

– Historic Structures Report

- History & Significance
- Character Defining Features
 (primary and secondary)
- Alterations
- Condition Observations
- Recommendations
- Cost Estimates
- Funding Opportunities



Overall Recommendations

- Secretary of the Interior Standards for the Treatment of Historic Properties

- Preservation
- Restoration
- Rehabilitation
- Reconstruction

- Stakeholder Insight

• April 2018

- Local Regulations

Clark County Code 40.250.030

- Building Code Considerations



Landscape Recommendations

- Historically Appropriate
 Materials
- Access/Use
- Drainage
- Screening
- Small Scale Features
- Vegetation Exhibits







Interpretive Trail




- Align rectilinear trail with agricultural use
- Connect to Hazel Dell Park
- Material and Color Palette
- Landscape Interpretation
- Plantings
- Viewpoints

Donated Wood Silo







Contributing Historic Resources



Administration



Garage



Milk House



Shop



Bunk House



Hog Barn



Cemetery (site)



Hazel Dell Park (site)



Machine Shed



Specific Recommendations

Immediate	Long Term
Minor	Maintenance
Immediate	Long Term
Major	Major



Administration Building (1926)

Current Use: Administration / Offices Approximate Area: 11,670 sq. ft.

Condition Observations:

- Water infiltration behind insulated panels
- Improper flashing over windows
- Organic growth of roof
- Unattached post and beam frame
- Water damage in basement laboratory

Overall Condition: Good





Administration Building (1926)

Overall Recommendation: Preservation/Restoration

Opportunities:

- Restore main entrance
- Second floor residential apartment




 Immediate – Minor Repair broken cornice return. Repair exterior wood trims and make watertight. Remove peeling paint and rust and repaint. Repair and repaint damaged interior doors. 	 Long Term – Minor/Maintenance Remove biological growth. Prevent animal infestation. Infill and repaint cracks in floors and ceilings.
 Immediate – Major Inspect and repair or replace EIFS system on south elevation's west wing. 	 Long Term – Major Restore the original main entrance. Evaluate post-and-beam structure for seismic capacity.

ΑΞϹΟΜ

Page 27

Overall Condition: Fair







Garage (1926)

Condition Observations:

- Cracking in structural tile on east elevation
- Cracking in structural tile under windows
- Organic growth of roof
- Crumbling mortar on window sills
- Broken wood window frame

Garage (1926) Overall Recommendation: Preservation/Rehabilitation

Opportunities:

 Classroom/Meeting space



 Immediate – Minor Repair missing horizontal board siding. Repair broken window frames. Prepare surfaces and repaint peeling paint and rust. Repair and finish exterior walls structural cracking. 	 Long Term – Minor/Maintenance Remove biological growth. Monitor structural cracks. Infill and repaint cracks in floor. Removed abandoned electrical wiring.
Immediate – Major • N/A	 Long Term – Major Finish walls and ceilings. Insulate building. Install new electrical system. Install new mechanical equipment.

Milk House (c. 1936)

Current Use: Fertilizer Storage Approximate Area:: 1,200 sq. ft.

Condition Observations:

- Structural cracking at southeast corner
- Cracking in exterior stucco
- Exposed structural tile
- Organic growth on foundation
- Rotting wood on doors

Overall Condition: Good





Milk House (c. 1936)

Overall Recommendations: Preservation/Rehabilitation

Opportunities:

- Classroom/meeting space (west)
- Restrooms (east)



Immediate – Minor	Long Term – Minor/Maintenance
 Replace rotting wood door panels. Repair and refinish structural cracking. 	 Remove biological growth. Repair damaged aluminum gutter Remove abandoned electrical wiring. Infill and repaint exterior cracks in stucco. Infill and repaint exposed structural block. Repair and repaint peeling paint. Infill and repaint cracks in floor and ceiling.
Immediate – Major	Long Term – Major
• N/A	Finish walls and ceilings.
	Insulate building.
	 Install new electrical system.
	 Install new mechanical equipment.

Agricultural Shop (1962)

Current Use: Agricultural Shop Approximate Area:: 980 sq. ft.

Condition Observations:

- Organic growth on foundation
- Rust on metal siding
- Rotting wood window frames
- Sagging ceiling wood boards
- Abandoned chimney openings

Overall Condition: Fair







Agricultural Shop (1962)

Overall Recommendation: Preservation

Opportunities:

 Maintain current use as a general purpose shop



 Immediate – Minor Repair rotting window frames. Replace sagging wood ceiling boards. Infill abandoned chimney opening. 	 Long Term – Minor/Maintenance Remove biological growth. Repair and replace wood windows. Infill cracks in floors. Remove abandoned electrical wiring. Replace wall panels.
Immediate – Major • N/A	 Long Term – Major Replace roof. Replace exterior metal panel siding.

Bunk House (c. 1925/c.1955)

Current Use: Vacant Approximate Area: 400 sq. ft.

Condition Observations:

- Lacks permanent foundation
- Leaning exterior walls
- Collapsing roof
- Sagging floor boards
- Collapsing ceiling
- No accessible entry (no stairs)

Overall Condition: Poor







Bunk House (c. 1925/c.1955)

Overall Recommendation: Reconstruction

Opportunities:

- Reconstruct building in original location
- Screen/secure utility equipment behind walls
- New use to farm users



Immediate – Minor	Long Term – Minor/Maintenance
 Secure entries to prevent unsafe access to building interior. 	 Interpret building's Poor Farm history.
Immediate – Major	Long Term – Major

Hog Barn (c.1920/c.1955)

Current Use: Produce Storage Approximate Area:: 1,420 sq. ft.

Condition Observations:

- Lacks permanent foundation
- Deficient foundation beams
- Sagging roof
- Rotting floor joists
- No accessible entry (no stairs)

Overall Condition: Poor





Hog Barn (c.1920/c.1955)

Overall Recommendation: Preservation

Opportunities:

 Maintain current use as storage



 Immediate – Minor Remove and repaint peeling paint. Replace missing windows. Replace rotting wood door. Repair rotting floor joists. Install formal entry. 	 Long Term – Minor/Maintenance Remove and repaint interior peeling paint. Remove abandoned electrical wiring.
Immediate – Major Replace foundation. Replace roof. 	Long Term – Major ● N/A

Machine Shed (c.1930)

Current Use: Storage Approximate Area: 1,230 sq. ft.

Condition Observations:

- Cracks in foundation
- Spalling concrete on foundation
- Rotting wood framing members
- Rotting wood siding
- Sagging and missing bay headers

Overall Condition: Fair





Machine Shed (c.1930)

Overall Recommendation: Preservation/Rehabilitation

Opportunities:

 Covered interpretation and public space on Interpretive Trail



Immediate – Minor	Long Term – Minor/Maintenance			
 Infill and repair foundation. Repair rotting wood posts. 	Remove biological growth.			
	 Repair and install missing bay headers. Remove and repaint peeling paint. 			
	 Repair rotting wood siding. 			
	Replace missing wood windows.			
	Remove abandoned electrical system.			
	 Interpret building's Poor Farm history. 			
Immediate – Major	Long Term – Major			
• N/A	Replace roof.			
	Finish walls and ceilings.			
	Insulate building.			
	Install new electrical system.			
	Install new mechanical equipment.			


Cemetery (1913) Current Use: Cemetery

Overall Condition: Good

Observations:

- Commemorative boulder at northwest corner
- Missing burial makers
- Wood fence delineates cemetery boundary
- Chain link fence at west end
- Vegetation abuts north access









Cemetery (1913) Overall Recommendation: Preservation

Opportunities:

- Consider relocation of commemorative boulder
- Research and install burial markers or interpretive map with names



Immediate – Minor	Long Term – Minor/Maintenance
Install interpretive sign.	 Identify and locate individuals buried in cemetery. Improve north access to cemetery. Consider relocation of commemorative boulder.
Immediate – Major	Long Term – Major
• N/A	• N/A

Hazel Dell Park Current Use: Cemetery

Observations:

– Security concerns

Recommendations:

- Security concerns
- Preserve wooded setting
- Interpret historic use and park development





Overall Condition: Good





Cost Estimates

Building	Recommendations	Cost \$/SF (includes soft cost)	Total Estimated cost (includes soft cost)
Administration Building (11,670 SF)	 Exterior Insulated Finish System Restoring front entrance Removing biological growth Seismic analysis Electrical work Other 	\$10/SF	\$116,731
Garage (960 SF)	 Exterior enclosure repairs (window/door) Remove biological growth Install ceiling/paint walls Lighting update Communication devices 	\$35/SF	\$34,344
Milk House (1,200 SF)	 Exterior enclosure repairs (doors) Install ceiling and paint walls Lighting update Communication devices 	\$33/SF	\$39,960
Agricultural Shop (980 SF)	 Replace exterior siding Window repair New roof Interior repairs and finishes cleaning 	\$85/SF	\$84,227

Cost Estimates

Building	Recommendations	Cost \$/SF (includes soft cost)	Total Estimated cost (includes soft cost)
Bunk House (400 SF)	 Demolition New foundation Framing and re-finishing existing siding New doors/windows New roof Interior work Electrical/lighting work/communications 	\$231/SF	\$92,454
Hog Barn (1,420 SF)	 New foundation Cleaning/paint New doors/windows New roof Cleaning/finishes Electrical/lighting work/communications Steps/misc. 	\$96/SF	\$136,638
Machine Shed (1,230 SF)	 Stabilizing foundation Re-finishing siding New windows New roof Interior cleaning/wood treatment Electrical/lighting/communications 	\$82/SF	\$101,412



Funding Opportunities

Funding Opportunities



Next Steps

- Address comments from Department of Archaeology and Historic Preservation
- Incorporate Preservation Plan with Master Plan and farm maintenance plan
- Prioritize future work
- Secure funding to initiate major projects



Clark County Community Planning

Jacqui Kamp Community Planning (564) 397-2280 ext. 4913 Jacqueline.Kamp@clark.gov

AECOM

Patience Stuart Architectural History (503) 948-7238 Patience.Stuart@aecom.com

